


CNC Vision Setup


This manual is designed to introduce the reader to the setup process of the CNC vision system, and some of its applications.

In order to set up the camera to work properly, you must go into the **CNC Settings > Camera**. The screen presented to you will be the one shown below:




Camera Interface allows to choose between a camera connected through a USB cord or through LAN. If the camera is connected through LAN, the **Initialization line** must list the correct IP address of the camera, while the USB channel is used if the camera is connected through a USB cord.

Region of interest (in pixels) signifies the area in which the camera is actively looking for markers, and should usually be set to be equal or slightly smaller than the actual resolution of the camera. When switching to the Camera tab, it can be seen that the region of interest is visually highlighted in yellow, as shown in the image below:



Marker size can be set experimentally to be slightly larger than the marker itself, in order to account for the visual transition between the marker and its surroundings. In the case of the particular marker used in this scenario, its size has been set to 160 pixels. NOTE: The camera focus must be properly adjusted in order for the camera to recognize markers.



Pixel to length coefficient is used to convert the pixels travelled into the actual physical distance moved, in mm. You are able to calibrate this for both the x- and the y-axes. In order to set up the

correct coefficient for your camera, use the Calibrate button in the Camera tab, or consult the full set of manual set up instructions below.

Tool number is usually assigned to be 10, however other tool numbers can be used if necessary.

Camera offset values are used to specify the distance from the camera to the working tool in the xy-plane.

Camera length value is used to specify the distance from the camera to the working tool tip in the z-axis.

Ignore decoder errors flag is set to OFF by default.

Camera Shift describes the distance the machine will move by if it does not locate a marker after it has been instructed to look for one. This can happen when the marker is not fully within the region of interest, and then the camera will keep on moving around until it either finds the marker or reaches the end of this specified Camera Shift.

Shift Speed describes the speed with which the machine is moving during its camera shift phase while trying to find the marker.

Pattern Match Level describes the level of parity with the original reference marker that each new marker must have for the system to recognize it. Higher numbers mean less parity (more differences between the markers), so as to avoid false positives it is advised to keep the numbers on the lower end of the scale. The graph below the Pattern Match Level indicates the parity levels during the machine search for markers, with the low points of the graph being indicative of the places where marker parity is highest (differences between new marker and reference are lowest).

Image sensor correction corrects for sensors with different aspect ratios. Use this if the marker image appears distorted or stretched when viewed through the Camera tab in myCNC software.

Setting up the pixel to length coefficients (older software versions)



The pixel to length coefficient is necessary for the camera to know how many millimeters it had moved after having traversed a certain number of pixel to the left/right/top/bottom of its original position. This procedure is done by finding the ratio of millimeters moved to pixels travelled. While it is automated in the newer versions of myCNC software, it can also be done manually in the older software versions.

In order to do so:


1. Go to the **Camera** tab of the myCNC software

Last update:


2019/07/02 quickstart:mycnc-quick-start:cnc-vision-setup <http://cnc42.com/quickstart/mycnc-quick-start/cnc-vision-setup?rev=1562084366>
12:19



2. Move your camera to the center of the marker and press the **Center** button




3. Press the **Start** and **Measure** buttons, and note the xy-position of the camera before moving it.



4. Move the camera some distance (in mm) and record that distance. Note the change from the original pixel xy-position, and find out how many pixels the camera has travelled over this movement. Divide the millimeters moved by the pixels travelled to obtain the pixel to length coefficient for each respective axis.

Last update:

2019/07/02 quickstart:mycnc-quick-start:cnc-vision-setup <http://cnc42.com/quickstart/mycnc-quick-start/cnc-vision-setup?rev=1562084366>
12:19




For example, in this setup, the machine has moved 12 mm to the right, while the x-position value has changed from 950 to 482.

$$950 - 482 = 468 \text{ pixels}$$

$$12 \text{ mm} \div 468 \text{ pixels} = 0.0256$$

Therefore, the pixel to length coefficient is 0.256

5. Input the new coefficient into the **CNC Settings > Camera > Pixel to length coefficient** and press **Save**



6. Repeat the procedure for the other axis.

After both axes have been calibrated, the machine will now have a proper coefficient of the number of pixels it moved by versus actual distance travelled in millimeters.

Using the hotkeys to move the camera


In order to move the camera straight from the Camera tab, a set of hotkeys have been designed specifically for that purpose. Note that the hotkeys are only present in the more recent versions of myCNC software. Please update if the camera hotkeys are not present in your profile version.

HOTKEY	ACTION
Arrow Up	Move in positive y-direction
Arrow Right	Move in positive x-direction
Arrow Down	Move in negative y-direction
Arrow Left	Move in negative x-direction
Space	Switch the step jog (00.1 through 1 mm)
Hold Control and Arrow keys	Move by the selected step jog


CNC Vision Example

The CNC Vision correction of a program to be used on a shifted or distorted working material can be done easily after the markers have been calibrated. In order to open and use a file with the CNC Vision system, use the following instructions:


1. From the myCNC software's main screen, click the Open DXF File button.




2. Select the particular DXF file you would like to open.
3. When selecting the tools, include Camera as one of the tools, and assign to it the same tool number as the one specified in the Camera Settings (this will be Tool 99 in our case). Assign the other tool or tools and their priorities as necessary for your particular program.



4. Once you have loaded the DXF file, the program should now have inserted the M397, M398, and M399 macros which refer to camera actions into the program G-code.



5. Press **Run**.



The machine will move the camera towards the supposed marker positions, and, if the markers are not immediately present in the Region of Interest, will move around this supposed marker position by the distance specified by the Camera Shift. After running through the camera macros and locating all of the markers for which the program has been calibrated, the program will automatically adjust for any shift or distortion that was introduced, and will immediately begin running the main program.

NOTE: The program will not begin the main cutting process unless all the markers that were expected to be adjusted for have been located.

Last update:

2019/07/02 quickstart:mycnc-quick-start:cnc-vision-setup <http://cnc42.com/quickstart/mycnc-quick-start/cnc-vision-setup?rev=1562084366>
12:19

From:

<http://cnc42.com/> - **myCNC Online Documentation**

Permanent link:

<http://cnc42.com/quickstart/mycnc-quick-start/cnc-vision-setup?rev=1562084366>

Last update: **2019/07/02 12:19**

