



Load NC-codes from USB drives under Linux

Goto **Settings manager**




Find **Removable drives and Media** Icon and open it



Check **Mount removable drives...** and **Mount removable media....**

press **close**



After it USB flash drives will be automatically mounted into the system folder **/media/operator** when inserted.

System automatically mounts flash drives into folder `/media/user_name`
user_name is your user name
for Tinkerboard images we provide the folder is
`/media/operator`

for LiveCD a default user name is "mycnc" and the folder is
`/media/mycnc`


If you change your user name, use this name accordingly

Goto **myCNC software Config Preferences NC code folders**


Add folder name where USB flash drives will be mounted -

/media/operator

and press **Save**



Now you should be able to open files directly from USB drive if search in
/media/operator/USB_drive_label folder



From:
<http://docs.pv-automation.com/> - myCNC Online Documentation

Permanent link:
<http://docs.pv-automation.com/quickstart/mycnc-load-nccodes-from-usb>

Last update: **2019/05/29 13:16**

